

For P C (U S B 2.0) surface inspector probe C I -1000-B



surface inspector probe C I - 1 0 0 0 - B

Size	$\phi 3.2 \text{ mm} \times 17.5 \text{ mm}$
View size	$\sim 400 \mu \text{ m} \times 300 \mu \text{ m}$
Focus	Manual adjustment maxium movable scope = 2mm
Magnification	400 power (more than 9 inch , only in PC case)
U S B	U S B For 1.1 or 2.0 For Windows2000/X P
ATT	Jack attachment (For both SC, FC and LC) Plug phenol attachment (For $\phi 1.25$ 、 $\phi 2.5$ and $\phi 2.5 \text{ APC}$) For P C soft ware (CD-ROM)

